



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

0001

April 20, 2009

Coleen Hackwell, Financial Analyst
State of Utah
Office of State Treasurer
E315 State Capitol Complex
Post Office Box 142315
Salt Lake City, Utah 84114-2315

Subject: Authorization for Release of Cash Deposit, Held by Utah State Treasurer, Release Amount \$1,000.00, DJN Rockwalls, Unpermitted Site, S/049/0056, Utah County, Utah

Dear Ms. Hackwell,

The Utah State Treasurer is presently holding funds in the amount of \$1,000.00, for the benefit of the State of Utah, Division of Oil, Gas and Mining as a form of reclamation surety for DJN Rockwalls Unpermitted site in Utah County.

The Division hereby requests the total release of funds in the amount of \$1,00.00 plus accrued interest, if any. Please make check payable to DJN Rockwalls, and remit the funds directly to the Division, attention: Minerals Regulatory Program.

If you have any questions or require further discussion regarding the content of this letter, please contact the Division, telephone (801) 538-5291 or email bondcoordinator@utah.gov.

Sincerely,

Dana Dean, P.E.
Associate Director of Mining

DD:lk:pb

cc: Penny Berry, DOGM
Lynn Kunzler, DOGM

PA\GROUPS\MINERALS\WP\M049-Utah\S0490056-DJN_unpermitted\bond\relcash_S0490056.doc



0001



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

June 10, 2008

Reviewed: _____

Mine Name: Unpermitted Mine	Permit Number: S/049/0056
Operator Name: DJN Rockwalls	Inspection Date: June 9, 2008
Inspector(s): Lynn Kunzler	Time: 2:00 pm
Other Participants: None	Mine Status: Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

Vegetation establishment is progressing nicely. Other than color difference on rocks that were scattered at the time of reclamation, I had difficulty finding the disturbed areas without the map. Species noted included crested wheatgrass, intermediate wheatgrass, sagebrush and sunflower. Cheatgrass was also present in abundance, but it is also dominant on the adjacent undisturbed areas. The amount of desirable vegetation (approximately 15% ground cover) is essentially the same on both disturbed area and adjacent areas.

Conclusions and Recommendations:

Continue to monitor this site when in the area. This site will be eligible for full release next year.

Inspector's Signature

LK:vs

O:\M049-Utah\S0490056-DJN_unpermitted\Inspections\Insp-06092008.doc